

OFFICE OF THE MUNICIPAL COUNCILLORS OF BANKURA

Ph. No- 03242- 250344/250367

Fax No- 03242- 259269/250367

Memo No- 612 /V-1

Date – 11.6.2016

NOTICE

Sealed quotations are hereby invited from bonfide , resourcefull Suppliers & contractors for supplying Mark-2 Tube Well Spare Parts within 20.6.16 by 2 pm. Positively and opened on the same day at 3 Pm. This Notice will be published in our website - bankuramunicipality.org

Terms & conditions are as follows :-

- (1) The rate should be quoted for the year 2016 -17.
- (2) Rate should be quoted including all taxes and the Authority reserves the right to accept or cancel any quotation without showing any reason .
- (3) the Authority reserves the right to cancel any materials of bad quality .
- (4) The agency should have supplier Licenses duly renewed.
- (5) PAN Number is required.
- (6) IT,ST.PT. clearance certificate duly renewed must be submitted along with the quotation paper.
- (7) Rs. 15,000/- (Fifteen thousand only) must be deposited in Cash before Submitting the quotation & original MR. submitted along with the quotation

Details of job to be done :-

- (1) Details of materials to be supplied as per Annexure List attached herewith.



Chairman  
Bankura Municipality  
11/6/16

Memo No-

Date—

Copy forwarded for information to:-

- (1) The Savadhipati, Bankura Zilla Parishad, Bankura
- (2) The District Magistrate, Bankura
- (3) The District Information Office, Bankura
- (4) The Executive Officer Bankura Municipality
- (5) The Accountant Bankura Municipality
- (6) The Head Clerk, Bankura Municipality
- (7) The respective file, B.M



Chairman  
Bankura Municipality  
11/6/16

**Bankura Municipality**  
**Annexure List of Mark II Tube Well Spares Sprats**

Notice No- 612/v-1

Date- 11.6.16

- 1] Mark II Tube Well Bucket ( PLI. /Rolex ) crome -----Rate of each
  - 2] Mark II Tube Well chain-----Rate of each
  - 3] Mark II Tube Well Axle ( Stainless steel )-----Rate of each
  - 4] Mark II Tube Well Rod Socket-----Rate of each
  - 5] Mark II Tube Well Connecting Rod ( Iron ) 12mm dia. ---Rate of each  
(10' Ft. length)
  - 6] Mark II Tube LS Ring-----Rate of each
  - 7] Mark II Tube Well Small Washer ( Foam)-----Rate of each
  - 8] Mark II Tube Well Big Washer ( Foam)-----Rate of each
  - 9] Mark II Tube Well Cylinder Lower Valve (GM)-----Rate of each
  - 10] Mark II Tube Well Plunger complete set (GM)-----Rate of each
  - 11] Mark II Tube Well Cylinder Complete (Brass inner)----Rate of each  
( FAIZ/BGS. make)
  - 12] Mark II Tube Well Head Assembly(GI) Weight-16 Kg.- Rate of each (complete set)
  - 13] Mark II Tube Well Water Tank (GI)Weight- 7Kg. ----Rate of each
  - 14] Mark II Tube Well Padestal ( GI )18 Kg -----Rate of each
  - 15] Mark II Tube Well Rubber Bucket -----Rate of each
  - 16] Mark II Tube Well Chain Nut -----Rate of each
  - 17] Mark II Tube Well -12mm x 40mm. Nut-bolt -----Rate of each
  - 18] Mark II Tube Well cylinder Rod-----Rate of each
  - 19] Mark II Tube Well 32mm GI Socket-----Rate of each
  - 20] Mark II Tube Well Plunger Weight ( GM )-----Rate of each
  - 21] Mark II Tube Well Bearing ( SKF) 6204-----Rate of each
  - 22] Mark II Tube Well Cylinder Barrel with Reducer cap-----Rate of each  
( FAIZ/BGS. make)
  - 23] Mark II Tube Well Reducer Cap-----Rate of each
  - 24] Mark II Tube Well Handle set (GI) ----- Rate of each
- All materials are of good quality.

SAE ( Water Works)  
Bankura Municipality

Arijit Datta  
10/06/2016  
Member  
Chairman-in-Council(WWD.) Bankura Municipality  
Bankura Municipality

M. Sanyal  
11.06.16  
Chairman  
Bankura Municipality