OFFICE OF THE MUNICIPAL COUNCILLORS OF BANKURA

Ph. No- 03242- 250344/250367 Fax No- 03242- 259269/250367

Memo No- 729 /V-1

Date - 23.06.16

NOTICE

Sealed quotations are hereby invited from bonafide, resourceful Suppliers & contractors for supplying Mark-2 Tube Well Spare Parts within 30.06.16 by 2 pm. Positively and opened on the same day at 3 Pm. This Notice will be published in our website - bankuramunicipality.org

Terms & conditions are as follows :-

- (1) The rate should be quoted for the year 2016 -17.
- (2) Rate should be quoted including all taxes and the Authority reserves the right to accept or cancel any quotation without showing any reason.
- (3) the Authority reserves the right to cancel any materials of bad quality.
- (4) The agency should have supplier Licenses duly renewed.
- (5) PAN Number is required.
- (6) IT,ST.PT. clearance certificate duly renewed must be submitted along with the quotation paper.
- (7) Rs. 15,000/- (Fifteen thousand only) must be deposited in Cash before Submitting the quotation & original MR. submitted along with the quotation

Details of job to be done :-

(1) Details of materials to be supplied as per Annexure List attached herewith.

Chairm ankura Municipality

Memo No-

Date-

Copy forwarded for information to:-

(1) The Savadhipati, Bankura Zilla Parishad, Bankura

(2) The District Magistrate, Bankura

(3) The District Information Office, Bankura

(4) The Executive Officer Bankura Municipality

(5) The Accountant Bankura Municipality

(6) The Head Clerk, Bankura Municpality

(7) The respective file, B.M.

(8) Notice Board, BM

Chairman
Bankura Municipality
Chairman
Bankura Municipality
Bankura

Bankura Municipality

Bankura Municipality Annexure List of Mark II Tube Well Spares Sprats

Notice No- 729 /V-1

Date- 23.6.2016

1] Mark II Tube Well Bucket (PLI. /Rolex) cromeRate of each
2] Mark II Tube Well chainRate of each
3] Mark II Tube Well Axle (Stainless steel)Rate of each
4] Mark II Tube Well Rod SocketRate of each
5] Mark II Tube Well Connecting Rod (Iron) 12mm dia Rate of each
(10' Ft. length)
6] Mark II Tube LS RingRate of each
7] Mark II Tube Well Small Washer (Foam)Rate of each
8] Mark II Tube Well Big Washer (Foam)Rate of each
9] Mark II Tube Well Cylinder Lower Valve (GM)Rate of each
10] Mark II Tube Well Plunger complete set (GM)Rate of each
11] Mark II Tube Well Cylinder Complete (Brass inner)Rate of each
(FAIZ/BGS. make)
12] Mark II Tube Well Head Assembly(GI) Weight-16 Kg Rate of each
13] Mark II Tube Well Water Tank (GI)Weihgt- 7KgRate of each
14] Mark II Tube Well Padestal (GI) 18 KgRate of each
15] Mark II Tube Well Rubber BucketRate of each
16] Mark II Tube Well Chain NutRate of each
17] Mark II Tube Well -12mm x 40mm. Nut-boltRate of each
18] Mark II Tube Well cylinder RodRate of each
19] Mark II Tube Well 32mm GI SocketRate of each
20] Mark II Tube Well Plunger Weight (GM)Rate of each
21] Mark II Tube Well Bearing (SKF) 6204Rate of each
22] Mark II Tube Well Cylinder Barrel with Reducer capRate of each
(FAIZ/BGS. make)
23] Mark II Tube Well Reducer CapRate of each
24] Mark II Tube Well Handle set (GI) Rate of each
All materials are of good quality.
1 Selet 10016
22/6/11 July of Dath ablants
SAE (Water Works) Bankura Municipality Chairman-in-Council(WWD.) Bankura Municipality
Bankura Municipality Chairman-in-Council(WWD.) Bankura Municipality
Bankura Municipality